



THE ULTIMATE TIME-SAVER: HOW TO SIMPLIFY YOUR CNC SETUPS

- ✓ **Reduce your setup times by implementing a standard modular system**
 - A typical setup time or change-over take just one hour
 - The method for setup is established the same way every time
 - The programmer determines the setup location
- ✓ **Improve your quality and accuracy by having simple, repeatable setups**
 - With precision bores on a tooling plate, you can count on repeatable setups from part to part. This is also very valuable if you have to put a part back up for a recut.
- ✓ **Increase the flexibility in your planning by having one modular system across many machining centers**
 - Promote creativity in your planning. This will allow you to adjust for constraints within your shop by increasing spindle utilization.
- ✓ **Increase your feeds and speeds with greater clamping force**
 - With superior holding force you can reduce your cycle time by 10%.
- ✓ **Machine all 5 sides of a block on your 5th axis mill**
 - Easily access 5 sides of your part on a 5th axis mill. This will allow you to reliably and accurately ensure all your features are in the right position to one another.

Many machine shops struggle with spindle inefficiency. WOW Workholding offers an efficient and predictable setup solution. Our customers are better prepared for their machining processes and, as a result, experience less stress in their manufacturing.

Simplify your setup. Use a WOW Workholding system • Get a quote • Call us for a free assessment

COMPETITION IS TOUGH • DON'T FALL BEHIND • WE HAVE A SOLUTION

Call us to review your application and find out how you can start saving time and money on your CNC mill setups

SCHEDULE AN APPOINTMENT



519-753-5422 | sales@riansolutions.com
92 Roy Blvd. Brantford, ON N3R 7K2
riansolutions.com

